

Topic: BIOS Limitation with Certain USB Flash Drives
Component(s) Affected: Model R2100 Dual Xeon CPU Blade
Date: January 14, 2004

OVERVIEW / ENVIRONMENT

The current release BIOS (1/14/04) is unable to see some flash drives that have an internal hub device. This is not a hub accessible to the outside world. Instead, it is part of the USB flash drive's controller chip.

DETAILED DESCRIPTION

Some USB flash drives are not BIOS bootable or accessible in DOS.

Note: This issue does not affect Windows.

RESOLUTION

Use a flash drive made by another manufacturer. Known working ones are Lexar JumpDrives, Disk-On-Key drives, Sceptre drives, and Unity ITS drives.

For more information, please contact ClearCube technical support.

support@clearcube.com
support.clearcube.com
(866) 652-3400
+1 (512) 652-3400

Email address for ClearCube Technical Support
ClearCube Support Website
Direct line in the US
Direct line from outside the US