

## **BIOS Upgrade History**

**BIOS32:** Initial Production release

**BIOS38:** Fixed non-customer related issues

**BIOS45:** Fixed bugs involving the use of certain PS2 keyboards which prevented booting or OS installation

**BIOS48:**

- 1) Enabled password security feature for BIOS “Setup” (F2).
- 2) Changed system default for power failure to “Power On” from “Last State”. This will guarantee system will come back up once power is restored.
- 3) Fixed bug where boot devices could not be disabled in “Setup”.