

Instructions:

Before using the patch you must edit the file so it will work properly.

Example:

If the source files reside on a floppy drive connected to the I/Port edit the the two lines within the batch file so they appear as below.

```
xcopy A:\IPort\CD-ROM\Windows\Inf\*. * c:\Windows\inf\
```

```
xcopy A:\IPort\CD-ROM\Windows\System32\drivers\*. * c:\Windows\System32\drivers\
```

“IPort-CDROM Patch.bat”

```
=====
```

```
@ echo off
```

```
:: Version number for this batch file  
SET MyVer=1.00
```

```
:: Display "About"  
ECHO I/Port USB Patch Written by ClearCube Technology
```

```
:: Display "Support"  
ECHO Contact Support if you need help at 866-652-3400 or support@clearcube.com
```

```
ECHO Make sure the batch file has been edited to match your source directory.  
Echo Press "Esc" to cancel..  
Pause
```

```
:: The line below copies the file "cdrom.inf" to the following directory on the I/Port C:\Windows\inf\  
xcopy x:\IPort\Patch\CD-ROM\Windows\inf\*. * c:\Windows\inf\
```

```
:: The line below copies three files (cdrom.sys, imapi.sys, redbook.sys) onto the I/Port on the following  
directory C:\Windows\System32\drivers  
xcopy x:\IPort\Patch\CD-ROM\Windows\system32\drivers\*. * c:\Windows\System32\drivers\
```

```
:End
```

```
=====
```

If you experience any problems please contact ClearCube Support at 866-652-3400 or email support at support@clearcube.com.